


INSTRUCTION SHEET



KEPCO An ISO 9001 Company.


**MA
RAX/AE
-1500H**

MOUNTING ADAPTER RAX/AE-1500H

DESCRIPTION. The Model MA RAX/AE-1500H Mounting Adapter includes an adapter plate and mounting screws that allow a horizontally-mounted 1500W AE power supply to be easily substituted for a horizontally-mounted 1500W RAX power supply. Mount the adapter plate to the AE power supply using the screws and spacers provided (see Figure 1), then install the adapter plate in place of the RAX power supply using the screws previously used to mount the RAX power supply.

NOTES:

1. MOUNT ADAPTER PLATE TO POWER SUPPLY AT HOLES "A" USING FOUR SPACERS P/N 104-0312, AND FOUR SCREWS P/N 101-0487.
2. REMOVE RAX POWER SUPPLY AND SAVE MOUNTING SCREWS, THEN INSTALL ADAPTER PLATE WITH AE POWER SUPPLY ATTACHED AT HOLES "B." USING MOUNTING SCREWS SAVED. (MOUNTING SCREWS ARE SEMS, M4 X 8, PHPH, LENGTH NOT TO EXCEED 8MM.)



3044689

FIGURE 1. ADAPTER PLATE INSTALLATION